

A Case Study of an ISG Failure Using a Time Domain TVA


John Srodawa



DISTRIBUTION STATEMENT A. Approved for public release; distribution is unlimited. OPSEC #: 8412

Application Description

- **Advanced Powertrain Demonstrator**
 - Engine
 - Opposed Piston Two Stroke Engine (OP2S)
 - Rated for 1000HP
 - Four Cylinders
 - Two crankshafts with combiner gearbox
 - Transmission
 - 32 Speed Binary Shift Steering Transmission
 - Integrated Starter Generator
 - 160kW Motor/Generator Unit
 - Sandwiched between engine and transmission
 - Doubles as the transmission bell housing
 - Used as the primary engine starter
 - Used to power vehicle's HV electrical bus



DISTRIBUTION STATEMENT A. Approved for public release; distribution is unlimited. OPSEC #: 8412




Application Description

32 Speed
Binary Shift
Transmission

160kW
ISG

OP2S
Engine




DISTRIBUTION STATEMENT A. Approved for public release; distribution is unlimited. OPSEC #: 8412



Application Description


- **Integrated Starter Generator (ISG)**
 - The ISG has no bearings
 - The stator is fixed to the transmission
 - Structurally ties engine to transmission
 - The rotor is supported by the transmission input shaft bearings
- **Torsional Coupling**
 - A Geislinger torsional coupling is packaged inside the rotor space claim
 - The Geislinger couples the engine output shaft to the transmission input shaft
 - The ISG rotor is downstream of the Geislinger
 - The ISG rotor is not directly tied to the engine shaft



DISTRIBUTION STATEMENT A. Approved for public release; distribution is unlimited. OPSEC #: 8412



Application Description




Rotor Assy

Transmission

Rotor Carrier Coupling

Stator and Housing Assy




Geislinger Coupling

DISTRIBUTION STATEMENT A. Approved for public release; distribution is unlimited. OPSEC #: 8412



Application Description



DISTRIBUTION STATEMENT A. Approved for public release; distribution is unlimited. OPSEC #: 8412



Application Description


POWER & MOBILITY

Stator Housing

ISG Rotor

Rotor Carrier
Coupling


Stator
Windings



DISTRIBUTION STATEMENT A. Approved for public release; distribution is unlimited. OPSEC #: 8412



Application Description






DISTRIBUTION STATEMENT A. Approved for public release; distribution is unlimited. OPSEC #: 8412



ISG Rotor Construction

POWER & MOBILITY



DISTRIBUTION STATEMENT A. Approved for public release; distribution is unlimited. OPSEC #: 8412




Failure Description

- **Loss of Resolver Signal**
 - Resulted in loss of inverter functionality
 - The ISG stayed in the powerpack as a passive device
- **Elevated Stator RTD Readings**
 - Several RTD's began indicating excessive winding temperatures even though the inverter was offline
- **Coolant Leak**
 - The air space surrounding the rotor and Geislinger coupling is sealed for powerpack submersion
 - A large volume of coolant was drained from this sealed air space
- **The powerpack was disassembled for ISG inspection**



Failure Description

Damaged
Coolant
Passage



Protruding
Screw Heads

DISTRIBUTION STATEMENT A. Approved for public release; distribution is unlimited. OPSEC #: 8412



Failure Description

POWER & MOBILITY



Nuts and Broken Bolts found in Debris



19 of 20 Rotor thru Bolts were found broken


Remaining thru Bolt was Loose

DISTRIBUTION STATEMENT A. Approved for public release; distribution is unlimited. OPSEC #: 8412



Failure Description

**Damaged
Coolant
Passage**



DISTRIBUTION STATEMENT A. Approved for public release; distribution is unlimited. OPSEC #: 8412




- **The bolted joint holding the rotor laminations together failed**
- **The loose screws and nuts became trapped between the rotor and the stator**
 - This led to broken coolant passages and electrical damage to the resolver and stator windings
 - Shorted stator windings led to a winding over temperature condition
 - Coolant leaking into the ISG air space was churned by the spinning rotor creating more heat
 - Damage to the coolant passages led to a loss of ISG cooling
- **Torsional vibrations became prime suspect since the ISG was tested extensively at the supplier under full load without any issues**



Bolted Joint Failure Mechanism

POWER & MOBILITY



- Alternating loads exceed bolted joint friction allowing for joint slippage
- Joint slippage causes bolt deformation which results in a total loss of joint clamp force
- The loose bolt is continuously hammered by the alternating forces until it breaks

DISTRIBUTION STATEMENT A. Approved for public release; distribution is unlimited. OPSEC #: 8412



- **Selection of Natural Frequency**
 - The spring rate of the Geislinger Coupling was selected to ensure that 4th order resonance was outside of the normal engine operating range
- **Crankshaft Integrity**
 - A frequency domain TVA was conducted to ensure that the crankshaft was safe from a fatigue standpoint
 - This frequency domain TVA was focused on normal engine operating speeds
- **Traditional design philosophy was followed**
 - Place the natural frequency of the driveline between engine cranking and engine idle speeds
 - The time spent accelerating from cranking speed to idle speed is too short to cause any real damage




Pre-Failure TVA

Engine Cranking Speed Range [0 to 250 RPM]

Allowable Resonance Zone [16 to 65Hz]

Design Natural Frequency [26Hz]

Engine Speed at Resonance [390 RPM]







DISTRIBUTION STATEMENT A. Approved for public release; distribution is unlimited. OPSEC #: 8412



Pre-Failure TVA

- Initial frequency domain torsional vibration analysis focused on the normal engine operating range
 - 800rpm to 2500rpm Crank
 - 900rpm to 2900rpm ISG
- The TVA was focused on engine gear train, crankshaft, and torsional coupling health
 - All design limits were met with margin
- Peak ISG deflection of 0.11 deg
 - This equates to $\sim 20 \text{ rad/s}^2$ at 26Hz
- There was no indication that the ISG would have issues




DISTRIBUTION STATEMENT A. Approved for public release; distribution is unlimited. OPSEC #: 8412




Post Failure TVA

- Engine Speed Traces Recorded from CAN Bus at 50Hz Sample Rate



Time [sec]
Normal Engine Start



Time [sec]
Low Fuel Rail Pressure Start


DISTRIBUTION STATEMENT A. Approved for public release; distribution is unlimited. OPSEC #: 8412



- **The amplitude of the vibrations and the number of cycles experienced during engine starting was surprising**
- **The CAN bus speed data shows limited fidelity due to the low sample rate**
 - Actual torsional behavior is likely more severe
- **This prompted the creation of a time domain torsional vibration model to obtain a better understanding of the torsional behavior**




- Mechanical Schematic of Engine / ISG System



DISTRIBUTION STATEMENT A. Approved for public release; distribution is unlimited. OPSEC #: 8412



- Schematic of Simplified Engine / ISG System for TVA Model




DISTRIBUTION STATEMENT A. Approved for public release; distribution is unlimited. OPSEC #: 8412



Post Failure TVA

- **Multi-cylinder time domain model**
 - The engine model is built on a simplified crankangle based cylinder model
 - The cylinder model is based on the polytropic process with an instantaneous heat release at TDC
 - The heat release was tuned to match the measured engine acceleration during normal starting events

Bore	130	mm
Stroke	135	mm
Conrod Length	226	mm
Clearance Volume	0.18	liters
Inlet Port Closure	115.4	deg BTDC
Exhaust Port Opening	115.4	deg ATDC
Polytropic Exponent	1.3	-
Peak Cylinder Pressure	38	bar




DISTRIBUTION STATEMENT A. Approved for public release; distribution is unlimited. OPSEC #: 8412




Post Failure TVA

- Multi-cylinder Crank Angle Engine Model



Torque Contribution from each Cylinder




Four Cylinder Engine Torque Trace

DISTRIBUTION STATEMENT A. Approved for public release; distribution is unlimited. OPSEC #: 8412



Post Failure TVA

Time Domain Model Results – Normal Engine Start




- Model predicts peak ISG rotor acceleration of 600 rad/s^2
 - Results in 2000 Nm reaction torque when applied to a rotor inertia of 3.3 kg-m^2
- 21 cycles in excess of 250 rad/s^2

DISTRIBUTION STATEMENT A. Approved for public release; distribution is unlimited. OPSEC #: 8412




Post Failure TVA

- Time Domain Model Results – ECU Data Comparison



Actual ECU CAN Data



Simulated ECU CAN Data

- TVA model results were discretized at 50Hz sample rate to simulate measured ECU CAN data with good correlation

DISTRIBUTION STATEMENT A. Approved for public release; distribution is unlimited. OPSEC #: 8412



- **The time domain TVA model revealed the true torsional environment of the ISG rotor**
- **Based on these results, the ISG rotor was redesigned to meet an angular acceleration requirement of 1500 rad/s²**
- **The redesigned rotor has been exposed to over 500 miles of in-vehicle operation without issue**
 - More than 300 engine starts



- **You must perform a TVA to predict the maximum angular acceleration at resonance**
 - The results are sensitive to the torsional damping of the system
 - Make sure you apply a healthy margin to the TVA predictions to protect against uncertainty in damping values
 - Applies to both ISG's and PTO driven machines
 - High Speed PTO driven machines can be worse due to amplitude amplification thru the gear ratio
- **Every new electric machine must have a peak angular acceleration requirement**
- **New integrations of existing machines must be designed to stay within the electric machine angular acceleration limits**



- **You cannot assume that the driveline will pass through resonance fast enough to avoid damage**
- **You cannot assume that the presence of a torsional damper between the engine and the electric machine will protect the machine from damage**
- **All bolted joints on rotating components must be designed against slippage at the peak angular acceleration seen in resonance**



- **You should design for an infinite life against fatigue in resonance**
- **You should perform a time domain TVA and assess total cycle accumulation when**
 - The materials used in rotating components do not have an endurance limit
 - You are unable to achieve infinite life due to other design constraints (weight, volume, inertia, etc.)



- **Assess cycle accumulation using Miner's Rule when infinite life is not possible**
 - Create a histogram of alternating stress conditions when passing thru resonance on each start and shut down
 - Examine vehicle usage profile to determine number of start/stop events per unit time
 - Anti-Idle capabilities significantly increase the number of start/stop events per day
 - Determine the cumulative effective cycles using Miner's Rule to determine time to fatigue failure




Don't Forget About Engine Misfire

Engine Cranking Speed Range [0 to 250 RPM]

Design Natural Frequency [26Hz]

4th Order Resonance [390 RPM]



1st Order Resonance [1460 RPM]

DISTRIBUTION STATEMENT A. Approved for public release; distribution is unlimited. OPSEC #: 8412

